

Fig. 1




Fig. 2




Fig.3




Fig.4

CHANGE IN SURFACE ROUGHNESS BEFORE  
AND AFTER HEAT TREATMENT IN VACUUM








Fig.5

(a)




(b)



# Fig.6

ENLARGED VIEW OF CORRUGATED FOIL



ENLARGED VIEW OF FLAT FOIL






Fig.7  
(a)



(b)





Fig.8





09/423944

Fig.9




Fig.10

